S-42 Myrtle Grove Oriole vicinity private Late eighteenth century, c. 1820

Dr. Henry Hyland's "Myrtle Grove" is situated on the west side of St. Peter's Creek near Oriole. The two-story frame house has an irregular five-bay facade that alludes to the complicated nature of its building history. The eastern two bays of the dwelling were clearly erected before the rest of the house, and the west wall of the original house was built in brick. The once exterior brick wall was later encased when the old house was reworked during the first quarter of the nineteenth century. Radical alterations included the relocation of the stair and chimney stack, as well as fully new interiors of Federal/Greek Revival woodwork. Fragments of eighteenth-century material remain on the second floor and in the cellar.

Dr. Henry Hyland was evidently responsible for financing the rebuilding of his father's house about the time of his marriage to Harriet E. Aires on April 6, 1819. Henry and Harriet Hyland occupied the rebuilt house until Henry's death in 1856. Harriet E. Hyland married William R. Ballard in 1865, and the couple maintained ownership of the property until 1881. William R. Ballard was a prominent resident in the Dames Quarter Election District with a 400-acre farm. In 1881, "Myrtle Grove" was sold to Annie A. Hyland (BFL 4/117), and in 1913 the farm passed out of family hands (SFD 65/457).

Earliest ownership of "Myrtle Grove," first known as "St. Peter's Neck," was held by Peter Elzey, who divided the tract between two daughters, Elizabeth and Frances. Elizabeth Elzey married Lewis Rigby, who transferred possession to John Rigby, and in turn, his daughter, Elizabeth Rigby, After Elizabeth's marriage to Lambert Hyland, the property remained under the Hyland name until the Kata nineteenth. century.

Maryland Historical Trust State Historic Sites Inventory Form

Survey No. S-42

Magi No. 2000425304

DOE __yes __no

1. Nan	le (indicate pr	referred name)		
historic Dr.	Hyland House			
and/or common	Mrytle Grove			
2. Loca				
street & number	r End of Annie Hyl	land Road		not for publication
city, town	Oriole	_X_ vicinity of	congressional district	First
state	Maryland	county	Somerset	
3. Clas	sification			
Category district X building(s) structure site object	Ownership public brivate both Public Acquisition in process being considered xnot applicable	Status _X_ occupied unoccupied work in progress Accessible yes: restricted yes: unrestricted no	Present Use agriculture commercial educational entertainment government industrial military	museum park X private residence religious scientific transportation other:
4. Own	er of Prope	rty (give names a	nd mailing addresse	es of <u>all</u> owners)
name Sn	owden and Susan Dor	sey		
street & number	Rt. 3 Box 144		telephone n	
city, town	Princess Anne	state	and zip code MD. 2	
		al Description		21853
-				
		k of Circuit Court		liber
street & number	Somerset County	Courthouse		folio
city, town	Princess Anne		state	MD. 21853
6. Rep	resentation	in Existing	Historical Surv	reys
title Mar	yland Historic Site	s Inventory		
date 196	7		federal _X_ stat	te county loca
depository for su	rvey records Maryla	nd Historical Trust		
city, town A	nnapolis		state	MD. 21401
			3.016	-

7.	Des	cri	pti	on
		_	_	

Survey No 5-42

Condition Check one Check one excellent deteriorated unaltered original site good ruins altered moved date of move fair unexposed	
---	--

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The Dr. Henry Hyland house stands at the end of Annie Hyland Road (also known as Crab Island Road) and on the west side of St. Peter's Creek near Oriole, Somerset County, Maryland. The two-story, five-bay frame house faces south with the principal gable oriented on an east/west axis.

Supported by an excavated cellar with Flemish and common bond brick walls, this two-story frame house appears to date from two principal periods, the late eighteenth century and the early nineteenth century. The eastern two bays of the house was clearly built before the rest of the dwelling with a two-story brick end wall. The brick wall now serves as an interior partition since the western three bays were added to the structure during the early to mid nineteenth century. Aside from a few fragments of eighteenth century style woodwork, the house interiors date from the first decades of the nineteenth century. Currently, the house is covered with aluminum siding, and a steeply pitched roof is sheathed with asphalt shingles.

The south (main) elevation is an uneven five-bay facade with a centralized entrance and flanking two-over-two sash windows. The front door is a replacement and aluminum shutters have been attached to each window. Cellar window openings with mortise and tenon frames and diamond cross-sectioned bars fill two openings that pierce the east foundation wall. The second floor is lighted by five unevenly spaced two-over-two sash windows.

The east gable end is partially covered by a shed roofed sun porch added to the house around 1976. A door was cut through the end wall to allow acces from the dining room. The second floor is lighted by two six-over-six sash windows, and a single six-over-six sash lights the attic. Rising from the gable end are twin chimney stacks finished with a slightly corbelled cap. The eaves to the roof extend from the wall surface and are finished with short returns.

The north (back) side of the main house is an uneven wall surface. Three bays with a west side entrance define the main block, while two additional bays are stepped in from the principal wall surface. The rear entrance is trimmed with a modern Colonial surround, and two-over-two sash windows light the first and second floors. In addition, two diamond cross-sectioned grilled openings pierce the foundation wall.

Upon first glance, the first floor follows a standard side hall/double pile plan, but a closer analysis suggests the house developed into this form beginning with an eighteenth century two-story, brick-ended house. The hall partition is a one-foot wide brick wall, while the other exterior walls are frame. Also, two corner stack supports remain in the cellar along the west wall, but brick chimneys no longer remain in these positions. Instead, twin chimneys rise against the east wall. Finally, a late eighteenth-century six-panel door with an ovolo molded surround and HL hinges survives on the second floor.

0. 3	igillicalice	Survey No	• S-42
1400 1500	storic archeology-pre -1499 archeology-hist -1599 agriculture -1699 architecture -1799 art -1899 commerce	oric conservation law economics literature education military engineering music exploration/settlement philosophy	chitecture religion science sculpture social/ humanitarian theater rnment transportation other (specify)
Specific	dates	Builder/Architect	
check:	Applicable Criteria: and/or Applicable Exception	ABCD .:ABCDEFG	
4-2	Level of Significance	e:nationalstatelocal	
Prepare support	both a summary parag	raph of significance and a general stat	ement of history and

Cianificance

The Dr. Henry Hyland house is an interesting example of an early nineteenth-century plantation house that incorporates the fragments of a late eighteenth-century brick-ended dwelling. The fragmentary aspects of the eighteenth-century material suggests a radical alteration during the early nineteenth century. It appears the brick end was reused as an interior partition, and an early nineteenth century house was built on the foundation of the earlier structure. Inside, the almost consistent Federal period woodwork suggests major rebuilding around 1810-1830. The estimated reconstruction might be at the later end of the bracket date due to the Greek Revival nature of the rlor and dining room mantels.

9. Major Bibliographical References

Survey No. S-42

10. Geograph	ical Data		
Acreage of nominated property Quadrangle name UTM References do NOT co		C	tuadrangle scale
A	Northing	B Zone Easting	Northing
C		D	
	1 - A'S' - A'		
Verbal boundary descriptio	n and justification		
Verbal boundary descriptio List all states and counties		pping state or county bou	ndaries
		pping state or county bou	n daries code
List all states and counties	for properties overl		
List all states and counties	for properties overl code code	county	code
List all states and counties state state 11. Form Pre	for properties overl code code	county	code
List all states and counties state state 11. Form Pre	code code	county county Historian	code
List all states and counties state state 11. Form Prepared Paul Touart corganization Somerset Counties	code code code pared By - Architectural	county county Historian	code

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust

Shaw House 21 State Circle

Annapolis, Maryland 21401

(301) 269-2438

The relative few eighteenth-century features and the fragmentary aspect of the brickded house suggests a radical alteration during the early nineteenth century. Accorded to the suggests a radical alteration during the early nineteenth canture. It may be that the early brick-ended house burned and the leftover remnants of the house, which would have been largely masonry, were redesigned in terms of a nineteenthcentury side hall/double pile house.

The side hall contains a Federal style stair that rises in an open flight to the attic in the northwest corner. A square newel post and three rectangular balusters to each tread support an oval profile handrail. The stringer is decorated with an unconventional stepend pattern, and the triangular area below the stringer is finished with vertical beaded boards. The stair rises in three flights to the attic.

From the hall access is provided to the two principal first floor rooms through slightly raised eight-panel doors, which are framed by thumb molded surrounds. Each doorway has paneled reveals. Both first floor rooms retain early nineteenth-century chair rail, base-boards, and mantels. The mantels in both rooms follow Greek Revival style designs with semi-detached Tuscan columns that support protruding frieze blocks and stepped broken shelves. The frieze blocks in the south room have a diamond design. Joining the two rooms are large ten-panel double doors framed by fluted surrounds with bullseye corner blocks. The niche to the left of the mantel in the north room (dining room) is filled with an eight-panel door closet.

The second floor is divided into three bedrooms which open off the upstairs hall. The rooms are simply finished with a combination of early nineteenth and a little late eighteenth-century woodwork. The attic has been finished off in modern times.

1. STATE HISTORIC AMERICAN BUIL

county Somerset

TOWN Manokin River CINITY Oriole
STREET NO.

ORIGINAL OWNER Dr. Henry Hyland ORIGINAL USE Dwelling PRESENT OWNER PRESENT USE Dwelling WALL CONSTRUCTION Clapboard NO. OF STORIES 21

HISTORIC AMERICAN BUILDINGS SURVEY INVENTORY

2. NAME Ayrtle Grove - Hyland House S-42
DATE OR PERIOD C. 1810-1820
STYLE
ARCHITECT
BUILDER

3. FOR LIBRARY OF CONGRESS USE

4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION

OPEN TO PUBLIC N_{O}

This is a large frame house of the Federal type. Unfortunately the interior was remodeled in the 1920's and most of the original panelling, with the exception of the staircase - which has unusually scrolled stepends - and a few doors, has been destroyed.

The house is three bays wide and 2 deep with an A-roof. All of the windows are modern. There are 2 chimneys enclosed within the 1eft end wall of the house.

Slave houses and other out buildings which were once on the property are now gone. The Hyland family cemetery is somewhere nearby, buried.

The original owner of this house was Dr. Henry Hyland. A saddle doctor of some local fame. Legend has it that he died in his saddle returning from a patients bedside - this horse brought him home.

5. PHYSICAL CONDITION OF STRUCTURE Endongered

Interio

Exterior

Altered

6. LOCATION MAP (Plan Optianal)


7. PHOTOGRAPH


PUBLISHED SOURCES (Author, Title, Pages)
 INTERVIEWS, RECORDS, PHOTOS, ETC.

9. Name, address and title of recorder Paul A. Brinkman

DATE OF RECORD

2/8/67







Myrtle Grove S-42
Oriole vicinity, Somerset Co., Md.
North Elevation
5/86, Paul Touart, Photographer
Neg./Md. Historical Trust



Myrtle Grove S-42
Oriole vicinity, Somerset Co., Md.
CCellar Grill
5/86, Paul Touart, Photographer

Neg./Md. Historical Trust



Myrtle Grove S-42
Oriole vicinity, Somerset Co., Md.
Mantel - Parlor
5/86, Paul Touart, Photographer
Neg./Md. Historical Trust




Myrtle Grove S-42
Oriole vicinity, Somerset Co., Md.
Mantel - Dining Room
5/86, Paul Touart, Photographer
Neg./Md. Historical Trust



Myrtle Grove S-42 Oriole vicinity, Somerset Co., Md. Stair 5/86, Paul Touart, Photographer Neg./Md. Historical Trust









Photographica by DANIEL C. CHURCH